

TO:		DATE: May 30, 2022
ADDRESS:		
ATTENTION: Bill Vanni		
WE TRANSMITT:	THE FOLLOWING:	FOR:
✓ Herewith	Drawings	Distribution
Under Separate Cover	✓ Inspection Reports	Approval
Overnight Delivery	Specifications	As Required
■ Fax	Review Comments	Fabrication

Repair Priorities

- C1P1 Emergency Condition Immediate Repair Required
- 1 C1P2 Critical Condition Repair ASAP
- 2 C2P3 Serious Condition Repair As Soon as Practical
- 3 C3P4 Deficient Condition Repair When Convenient
- 4 C4P5 Maintenance Condition Repair When Convenient
- 5 C5P6 For Record Only No repair required

© SIMMS 1998 Repair Priorities 5/30/2022 1:23:30 PM

<u>l n s p e</u>	ction	Grou	ıp R	<u>e pair</u>	С	o s	t :	<u>S u</u>	mmary	, By Re	pair	Priori	t y		
		Structural	Asset condition	Deficiency Quantity by Priority						Repair	Repair Cost Estimate by Priority				
EQUIPMENT NAME STEELPOOR	EQUIP. ID	Condition	(Level)	0 1	2	3	4	5	TOTAL	0 1	2	3	4	TOTAL	
Caster Slab Yard, Caster Slab Handling Building [0001053]	3213-401-00-00	Poor			141	19	43	8	211		302,480.	18,110.	44,080.	364,670.	
BOF External Hot Metal Desulfurization, Desulfurization Building and Station [0001093]	2012-403-00-00	Poor			5	3	2		10		64,830.	10,266.	150.	75,246.	
BOF Vessels, BOF, Scrap Yard Building [0201026]	2018-402-10-00	Poor		10	21	18	17	1	67	19,650.	34,840.	16,270.	4,770.	75,530.	
BOF Vessels, BOF, Service Floor Beams Above Vessels [0201044]	2018-402-12-00	Poor			5				5		8,830.			8,830.	
5 BOF Precipitator, BOF Dirty Gas System, Precipitator Header, East Roadway Support Beams [0301045]	2034-486-00-01	Poor			13	8	8		29		23,200.	6,320.	5,440.	34,960.	

© SIMMS 1999 - Transmittal 990101 Page 1 of 2

6 #1 Continuous Slab Casting Machine, Spray Chamber [0301054]	2714-429-00-00	Poor		13	1			14		50,500.	3,400.		53,900.
7 Blooming Mill Slab Yard, Crane #197 [0301056]	3113-415-00-00	Poor		5	9		4	18		3,710.	3,540.		7,250.
BOF Vessels, BOF, Roof Ventilators [0301070]	2018-402-08-00	Poor	1	7	18	13		39	800.	8,140.	17,620.	8,000.	34,560.
9 BOF Precipitator, BOF Dirty Gas System, Top Horizontal Duct [0301085]	2034-486-01-00	Poor		8	1			9		80,950.	1,200.		82,150.
10 80" Hot Strip Slab Yard, Slab Storage Building [0301094]	3322-401-00-00	Poor	3:	20	100	150	4	574		365,800.	48,130.	22,450.	436,380.
Inspection Group: STEELPOOR Total:			11 5	38	177	233	17	<u>976</u>	20,450.	943,280.	124,856.	84,890.	<u>1,173,476.</u>

Very truly yours, Structural Design Corporation

ĸ	v	•		
$\mathbf{\mathcal{L}}$		•		

Bill Vanni

© SIMMS 1999 - Transmittal 990101 Page 2 of 2